



BROOKS ROAD LANDFILL SITE  
Halimand County, Ontario  
GEOLOGY AND HYDROGEOLOGY ASSESSMENT REPORT  
VERTICAL CAPACITY EXPANSION ENVIRONMENTAL ASSESSMENT  
CROSS SECTION PLAN

18235-20  
Apr 6, 2017




Figure 1



BROOKS ROAD LANDFILL SITE  
Halimand County, Ontario  
GEOLOGY AND HYDROGEOLOGY ASSESSMENT REPORT  
VERTICAL CAPACITY EXPANSION ENVIRONMENTAL ASSESSMENT  
GEOLOGICAL CROSS-SECTION A-A'


18235-20  
Apr 6, 2017

Figure 2



**NOTES:**


\* ABANDONED WELL - HISTORICAL DATA



BROOKS ROAD LANDFILL SITE  
Halimand County, Ontario  
GEOLOGY AND HYDROGEOLOGY ASSESSMENT REPORT  
VERTICAL CAPACITY EXPANSION ENVIRONMENTAL ASSESSMENT  
**GEOLOGICAL CROSS-SECTION B-B'**

18235-20  
Apr 6, 2017

Figure 3



**Figure 4**  
**2016 EXISTING CONDITIONS**  
**2016 OPERATIONS AND MONITORING REPORT**  
**BROOKS ROAD LANDFILL SITE**  
*Haldimand County, Ontario*

